



Product Change Notice (PCN)

Date: 06/28/2021

PCN Number: PCN-0360171R-01

To Our Customers:

We appreciate your use of CUI products. Our commitment in maintaining and improving processes is demonstrated by plans to enhance our product quality, reliability and manufacturability. The purpose of this notice is to inform you of a product change.

Product(s) Affected: SDI200G-U, SDI200G-UD, SDI160G-U & SDI160G-UD Series

SDI200G-12-U-P51	SDI200G-19-UD-P51	SDI160G-56-U2-P51
SDI200G-18-U-P51	SDI200G-19.5-UD-P51	SDI160G-12-UD-P51
SDI200G-19-U-P51	SDI200G-20-UD-P51	SDI160G-19-UD-P51
SDI200G-19.5-U-P51	SDI200G-24-UD-P51	SDI160G-24-UD-P51
SDI200G-20-U-P51	SDI200G-48-UD-P51	SDI160G-48-UD-P51
SDI200G-24-U-P51	SDI200G-56-UD-P51	SDI160G-56-UD-P51
SDI200G-48-U-P51	SDI200G-12-UDC-P51	SDI160G-12-UDC-P51
SDI200G-56-U-P51	SDI200G-18-UDC-P51	SDI160G-19-UDC-P51
SDI200G-12-UC-P51	SDI200G-19-UDC-P51	SDI160G-24-UDC-P51
SDI200G-18-UC-P51	SDI200G-19.5-UDC-P51	SDI160G-48-UDC-P51
SDI200G-19-UC-P51	SDI200G-20-UDC-P51	SDI160G-56-UDC-P51
SDI200G-19.5-UC-P51	SDI200G-24-UDC-P51	SDI160G-12-UD2-P51
SDI200G-20-UC-P51	SDI200G-48-UDC-P51	SDI160G-19-UD2-P51
SDI200G-24-UC-P51	SDI200G-56-UDC-P51	SDI160G-24-UD2-P51
SDI200G-48-UC-P51	SDI200G-12-UD2-P51	SDI160G-48-UD2-P51
SDI200G-56-UC-P51	SDI200G-18-UD2-P51	SDI160G-56-UD2-P51
SDI200G-12-U2-P51	SDI200G-19-UD2-P51	SDI160G-12-U-P51
SDI200G-18-U2-P51	SDI200G-19.5-UD2-P51	SDI160G-19-U-P51
SDI200G-19-U2-P51	SDI200G-20-UD2-P51	SDI160G-24-U-P51
SDI200G-19.5-U2-P51	SDI200G-24-UD2-P51	SDI160G-48-U-P51
SDI200G-20-U2-P51	SDI200G-48-UD2-P51	SDI160G-56-U-P51
SDI200G-24-U2-P51	SDI200G-56-UD2-P51	SDI160G-12-UC-P51
SDI200G-48-U2-P51	SDI160G-12-U2-P51	SDI160G-19-UC-P51
SDI200G-56-U2-P51	SDI160G-19-U2-P51	SDI160G-24-UC-P51
SDI200G-12-UD-P51	SDI160G-24-U2-P51	SDI160G-48-UC-P51
SDI200G-18-UD-P51	SDI160G-48-U2-P51	SDI160G-56-UC-P51



20050 SW 112th Ave. Tualatin, Oregon 9706
phone: 800.275.4899 fax: 503.612.238
www.cui.com

Reason(s) for Change: DC cable updated to UL2464.

Description of Change: DC cable was UL2095, we are now updating these series to UL2464.

Affected Date Code: 2119

Product Availability: Currently available

Additional Information: No change to fit or function. Form has been changed.

PCN Approval:

Operations/Quality

A handwritten signature in black ink, appearing to read "Sam Wood".

Product Marketing

A handwritten signature in black ink, appearing to read "Morgan".